Flexible Abrasives - SCM belts



PREMIUM LOW STRETCH **SCM** belts















for universal use

Application

+ For reducing surface roughness, smoothing surfaces as well as cleaning and removing welding seams using stationary belt grinders

We recommend

- "MEDIUM" grain for cleaning, for removing rust and coatings and for final finishing
- "VERY FINE" grain for gentle cleaning, for removing burrs and for final finishing
- + "ULTRA FINE" grain as the final step

Advantage

- + Specially developed in order to avoid stretching during work
- + Special design for exceptional durability
- + Robust structure for maximum lifetime

Form		Type number	Dimension	Specification	PU
6	BELT-VL	34049732	75 x 2000	SCM A MEDIUM	5 Pcs.
		34049734	75 x 2000	SCM A VERY-FINE	5 Pcs.
		34561752	75 x 2000	SCM S ULTRA FINE	5 Pcs.